# Oil Field Environmental Incident Summary

**Responsible Party:** STATOIL OIL & GAS LP **Well Operator:** STATOIL OIL & GAS LP

Well Name: IRGENS 27-34 #8H

Field Name: EAST FORK Well File #: 30701

Date Incident:2/20/2016Time Incident:10:00Facility ID Number:County:WILLIAMSTwp:156Rng:100Sec:34Qtr:

Location Description: Spill was contained on location

Submitted By: Stephen Sypult Received By:

Contact Person: Jim Haugen

6300 BRIDGE POINT PKY, BLDG 2

SUITE 500

AUSTIN, TX 78730

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 5 Barrels 5 Barrels

**Brine** 

Other

### **Description of Other Released Contaminant:**

Crude Oil released through flare after a high-level alarm shut in the well and control valves in the flow line to the guad packs.

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

Serious risk for hydrocarbons to ignite as they left the flare.

Areal Extent:

## Potential Environmental Impacts:

Minimal risk from direct contact, but serious risk of fire if hydrocarbons ignited.

## Action Taken or Planned:

Currently, the wells are shut-in and a further investigation has been prompted to investigate the design for the re-direction of fluids through the flare.

Wastes Disposal Location: Phillips and Jordan took to our profiled waste facility

Agencies Involved:

#### **Updates**

Date: 2/23/2016 Status: Reviewed - Assigned to Other Agency Author: Espe, Brady

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.